

General Environmental Incident Summary

Incident: 3354 **Date/Time Notice:** 6/17/2014 1020 **DEM Incident No:**
Responsible Party: Pioneer Well Services
Date Incident: 6/16/2014 **Time Incident:** 2000 **Duration:** 2 hours
County: McKenzie **Twp:** 152 **Rng:** 101 **Sec:** 13 **Qtr:**
Lat: 47.97866 **Long:** -103.55890 **Method:** Interpolation from map
Location Description: Mckenzie Co 29- 6 miles east of highway 85

Submitted By: Todd Beard **Affiliation:**
Address: PO Box 908
119 Well St E
City: Williston **State:** ND **Zip:** 58802-0908

Received By:

Contact Person: Todd Beard
PO Box 908
119 Well St E
Williston, ND 58802-0908

Distance Nearest Occupied Building: 2 Miles **Release Contained:** Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: Antifreeze (engine coolant)

Volume Spilled: 2.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

motor vehicle accident created leak in cooling system

Risk Evaluation:

none

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

potential rain runoff

Action Taken or Planned:

contaminated gravel and dirt removed

Wastes Disposal Location:

Agencies Involved: Local Law Enforcement

Updates

Date: 6/17/2014

Status: Reviewed; No Followup Required

Staff: Roberts, Kris

Updated Volume:

Notes:

Report of anti-freeze release due to vehicle accident included that the impacted soil had been removed. Due to small volume and report of soil removal, no followup is necessary.